Refresh Data

Refresh Data at anytime to

Run a Snap Shot

Run Snap Shot at the end of

**Dashboard Summary Notes:** 

Total Assets is calculated independently, however the sum of 'On Programme', 'Off Programme' and 'Validation Required' should equal 'Total Assets'.

Volume Change in 'Asset Count' is based on last Management Summary Report.

%Change Columns display a percentage change from current compliance against an back-dated 'point in time' copy of

	Properties					Con	npliance			
	Total Assets	On Programme	Off Programme	Validation Required	Compliant	Non-compliant	Current Compliance	%Change / Weekly Snap- Shot	%Change / Last - Management Report	
Change in Asset Count 71				Domesti	ic Dwellings					Comments
Gas (LGSR Programme) In Date	5672	4599	232	841	4599	0	100.00%	→ 0.00%	→ 0.00%	Units in 'Validation Required' is ongoing work in progress.
CO Detection Installed (Y/N)	5672	4623	217	832	4510	113	97.56%	→ 0.00%	<b>1</b> .08%	Units in 'Validation Required' is ongoing work in progress.
Electric (5-Yr EICR Programme) In Date	5672	5520	131	21	5385	135	97.55%	→ 0.00%	• 0.03%	Validation Complete: New Validations are from new assets added wk/commencing 08/01
Smoke Detection Installed (Y/N)	5672	5520	131	21	5273	247	95.53%	→ 0.00%	<b>4</b> .47%	Validation Complete: Validations are from new assets added wk/commencing 08/01
Change in Asset Count <b>2</b>				Communal B	locks & Schem	nes				
Gas (LGSR Programme)	268	8	260	0	8	0	100.00%	→ 0.00%	→ 0.00%	Validation Complete:
Electric (5-Yr EICR Programme)	268	256	12	0	255	1	99.61%	→ 0.00%	→ 0.00%	Validation Complete: *1 Non-Compliant = Tannery Court Block. Mobilising for full rewire in FY 2023/24
Fire Risk Assessment	268	264	0	4	143	121	54.17%	→ 0.00%	1.04%	Validation Complete: Agree with FSLead on method for recording reviews of RA's. *4 New FRA's required.
Asbestos Management	268	264	4	v2.4 Update - TBC	0	264	0.00%	→ 0.00%	→ 0.00%	***Yet to update Data held on Contractor Web Portal.
Water Hygiene (Legionella) Risk Assessment	268	15	253	0	0	15	0.00%	→ 0.00%	→ 0.00%	Validation Complete: Agree with BSLead on method for recording reviews of RA's.
Lifts Full Inspection	25	25	0	v2.3 Update - TBC	23	2	92.00%	→ 0.00%	→ 0.00%	***Yet to update Two 'Non-Compliant' are currently out of service for refurbishment - Update query to recognise as 'Off Plan'.
Change in Asset Count >0				Commu	nity Centres					
Gas (LGSR Programme)	4	4	0	0	4	0	100.00%	→ 0.00%	→ 0.00%	Validation Complete:
Electric (5-Yr EICR Programme)	4	4	0	0	4	0	100.00%	→ 0.00%	→ 0.00%	Validation Complete:
Fire Risk Assessment	4	4	0	0	4	0	100.00%	→ 0.00%	→ 0.00%	Validation Complete: Agree with FSLead on method for recording reviews of RA's.
Asbestos Management	4	4	0	v2.4 Update - TBC	0	4	0.00%	→ 0.00%	→ 0.00%	***Yet to update Data held on Contractor Web Portal.
Water Hygiene (Legionella) Risk Assessment	4	4	0	0	1	3	25.00%	→ 0.00%	→ 0.00%	Validation Complete: Agree with BSLead on method for recording reviews of RA's.

## Fire Safety Outstanding Actions Summary:

		Risk		
Block Architype	High	Medium	Low	Comments
High Rise 18+	1	45	11	High risk: One action which is currently in progress Extend the automatic fire detection inside the electric cupboards for early warning and ensure persons inside the apartments next to it are alerted immediately. Overdue since July 22 waiting documentary evidence of completion following the contractor visit in November 23. Medium risk outstanding since July/August/October 22 in varying positions of action with all actions expected to be complete within 6 months. Low risk outstanding and overdue since October 22 expected to be complete by March 24
Medium Rise 11-18	26	119	16	High risk outstanding and overdue since August 2022 (see below list of issues), Medium risk outstanding and overdue since October 2022. The high-risk actions fall within two common themes primarily: 9 inspection of roof void access and electrical intake cupboards. Surveys have been commissioned; 6 regarding reviewing fire action notices and visiting staff training records.
Low Rise Combined	464	2086	298	High risk outstanding and overdue since August to October 2022. Medium risk outstanding and overdue since July 2022. Low risk outstanding and overdue since April 2023. No date 645.  There are no life critical actions at any of the buildings.  The majority of high-risk actions are non-fabric related.  The high-risk actions within the Low rise fall into several common themes:  -87 actions concern 'management confirm that the common area fixed electrical system has been inspected and tested within the last 5 years in accordance with BS7671:2008 (as amended). The position is that the reinspection is complete however we have not closed down the actions as we are waiting the certification being provided.  - Numerous actions concern 'residents must be reminded of the importance of keeping doors closed' the position is that residents will be receiving this information in the Christmas newsletter 2023.  - 22 actions relate to 'fire safety signage to be reviewed' The position is that we are in the process of reviewing and upgrading and will have this work completed within 6 months.  - 77 actions relate to fire door surveys of doors. The position is that surveying has started with additional resources being put in place. Communal doors of the high rise, 11-18m buildings and 42 low rise buildings are now completed. The aim is for this work to be completed within the next 12 months.
Sheltered	30	91	14	High risk outstanding and overdue since May 22. Medium risk outstanding and overdue since July 2022. Low risk outstanding and overdue since October 2022. The high-risk actions within the Sheltered fall into several common themes primarily: - 15 actions around roof void access and compartmentation. The survey for which has been commissioned. 6 actions relating to reviewing signage and 5 other issue relates to logging the training of staff which is also in progress.
Christine Ledger Square	17	55	3	